

Reconnaissance of damaged structures after the 2016 Muisne-Ecuador Earthquake



Dept. of Civil, Structural and Environmental Engineering University at Buffalo, State University of New York: Jerome S. O'Connor, PE, F.ASCE, Executive Director Bridge Institute and Enrique Morales Moncayo, Ph.D candidate.

OUTLINE

Introduction

Part I: Seismic hazard-2016 Muisne Ecuador Earthquake

Part II: Structural reconnaissance-Damage

Part III: Nonstructural reconnaissance-Damage

Part IV:

Part V: Conclusion





At 18:58:37 local time off-shore of the west coast of northern of Ecuador







Source:emapsworld

Mw=7.8 on 16th April at 18:58,depth=19km





Largest Eartquakes (1906)# 7 Off the Coast of Ecuador(USGS).





The event occurred near the boundary zone between the Nazca and the South American plates(Toulkeridis, 2013)



Figura 4. Concentración histórica de sismos en Ecuador Fuente. Registro histórico IG. Geodynamic setting of Ecuador, the Galapagos Islands and the Carnegie Ridge. Adapted from Toulkeridis, 2013



Near twenty Ecuadorian volcanoes are considered to be active for the last century, five of these erupted in the last 17 years. Left: Eruption of Guagua Pichincha (0°10'14.88"S, 78°36'45.36"W) on October 7th, 1999; Upper right: Typical smaller and frequent eruption of Tungurahua in 2002 (1°28'12.71"S, 78°26'41.28"W); Centrer: Eruption of Sangay in 2001 (2°00'17.99"S, 78°20'26.88"W); Lower right: Biggest eruption in past decades of Reventador in 2002 (0°04'39.00"S, 77°39'20.87"W). Photos by Alois Speck and Anonymous (Reventador).



HUMANS





earthquake left 667 fatalities, over 16000 injured and 20000 displaced.

ECONOMICS









Damage Assessment/Tagging/Incorporation of ATC-20

The document has been adapted for the evaluation of buildings damaged during this earthquake (damage and conditions of a building).





SOURCE: IGM



SOURCE: IGM

G..



SOURCE: IGM

Damage report from IGM





Porcentaje de construcciones afectadas y destruidas por localidad con respecto al total del país, 16/04/16



Damage report from GEER

Esmeraidas (70km) Fepicenter Pedernaes (30km) Ganto Domingo (110km) Manta (50km) Manta (50km) Ochone (120km) Manta (50km) Ochone (120km)

SOURCE: GEER



Contours of Intensity from USGS and strong motion stations (SMS) color coded by the intensity of the motion in terms of the geo-mean peak ground acceleration (PGA) and Acceleration time series in the EW and NS component overlying a map of Ecuador with the main cities and stations.



 Response Spectrum and Code-Based Design Spectra NEC-2015 (a return period 475yr prob. of exceedance of 10% in 50 years)



Ground motions provided by the Seismology Department, instituto Geofísico, Escuela Politecnica Nacional, Ecuador with details in their report Singaucho, J., Laurendeau, A., Viracucha, C., Ruiz, M. (2016). "Observaciones del Sismo del 16 de Abril de 2016 de Magnitud Mw 7.8"

• Response Spectrum. NEC-2015 (475yr)



Response Spectrum RENAC and NEC15

Ground motions provided by the Seismology Department, Instituto Geofísico, Escuela Politecnica Nacional, Ecuador with details in their report Singaucho, J., Laurendeau, A., Viracucha, C., Ruiz, M. (2016). "Observaciones del Sismo del 16 de Abril de 2016 de Magnitud Mw 7.8"

Housing and building inventory and Construction- This presents the type of buildings in the

area affected by the earthquake

Wood houses



Residential Building with commercial first floor



Reinforced Concrete Building









There were several buildings that completely collapsed

Portoviejo

Pedernales

Bahia de Caráquez



SOURCE: GOOGLE

SOURCE: EL COMERCIO

SOURCE: UB TEAM

Portoviejo(170km, PGA=0.37g)

Ecuatorian Institute Social Security





Main structural Observation The damage at each building was dependent on the structural system, poor seismic detailing, poor construction practices, quality of materials, and intensity of the ground motion.

Portoviejo

Manta

Bahia de Caráquez

Soft Story failure. The first floor of these buildings collapsed







Main structural Observation

Sings of several corrosion on reinforced steel, collapsed electrical pole with corrosion and reduction of effective area of longitudinal steel.







Hospitals

Plastic hinges formed in the columns of the buildings and residential houses. The masonry walls between columns restrained the column height and increases the shear demand when the plastic flexural demand concentrated at their ends.





Main structural Observation

Reinforced concrete detailing:

Stirrup spacing and discontinuity in the longitudinal rebars were observed in columns of some older multistory moment frame buildings.



Main structural Observation

Liquefaction –Soild Failure:

The settlement caused some building to sink.



Main nonstructural Observation

This Building/hospital suffered no structural damage, the building/hospital was completely closed because there was an extensive nonstructural damage related to nonstructural elements that are sensitive to drifts and acceleration.

• Drift

• Acceleration:









Hospitals and health infrastructure

Although none of the hospital facilities collapsed, 22 were left inoperative in the province of Manabí and Esmeraldas due to severe damage to non-structural components. Medical assistance was provided from temporary shelters, resulting in overcrowding, lack of sanitation and increasing risk of epidemic disease transmission.

IESS Hospital Manta

Solca Hospital Portoviejo

Hospital Chone

Bahia Hospital

















Main Nonstructural Observation

Masonry infill- Outpatient

Ducts and ceilings







Nonstructural damage





Main nonstructural Observation



ASSESSMENT OF NONSTRUCTURAL COMPONENTS OF TWO HOSPITALS IN ECUADOR

FOR POTENTIAL SEISMIC HAZARD IN ACOORDANCE WITH FEMA E-74.



FEMA E -74 METHODOLOGY

Parapet

Nonstructural architectural component must be secured as it is located on the upper parts of the houghtal, overlooking structur below:





The unreinforced matomy parapets are prose to failure due to their height and idendement, as forcer in the earthquake are generated at the bare causing cracks and collapsing the structure.

Anchor Method

-

Consequences Parapet failing from heights are dangeroun destroying everything that lies lowsaft them. Persons moving in or out of the building are at risk of desth. There is the added risk of further destruction to elements such as cars, inschaelical equipment, etc.



This endraces the structure at a maximum distance of 6° from the traj, performed by drilling metal sections through the piecapet and steel pieces. secured and adjusted with holts braces or diagonal angle profiles are aschored to the roof plates, wither welded to botted.

The parapets should be fastiened to the celling or floor to prevent falling. Spaced strutu are used.

Anthorages must be designed to that they can withstand the forces caused by the warthquake. The natur clamp plate can be painted or otherwise finished in a way that is constraint with the facade of the building.

12% A Phone Example 274 (6.3.5.3.4) Experience Required An engineer shall design the anthoring system.

Recommended Priority Life safety, property han: Falling elements can cause deaths.

Implementation Cont and Disruption.

Implementation, cost is moderate, involves labor and manopy materials such at angle sections, both, and welds. Disruption to hospital activity is minimal for this work show the main work to be done is on terraceit and roofs.

Emergency Generator

ed for electricity in an emergency.



This system is needed to address the lack of electricity caused by interruption to external power supply. Strong movements may cause the generator to move and break connections, still important to check with them.



Emergency generators are essential equipment for the hospital, without good anchorage they can slip or tip.

Consequences Damage caused to the wiring, fuel lines, etc., function and operation of the equipment is compromised or ut of service, causing failure in the electrical system and complicating the operation of the hospital after an earthquake.





Place base arolators to control movement, reduce deformations and forces, ensuring the preservation and

Piper must be dealble connections to diage



Required Experience Engineer to calculate the auchdrage

Recommended Priority Safety of life, loss of function and use of equipment post-earthquake in high.

Implementation Cost and Disruption. Implementation cost is low: labor involves manuary, reinforcing steel, boing etc. The disruption to bospital function is sull and to equipment minimal.

Dialysis Unit

Masonry walls. plaster ceiling, lamps. floor. dialysis equipment and supplies as part of architectural considerations and medical requirements in the Dialysis Unit



Strong movements may lead to dialysis equipment slipping and the connections thereof breaking. Critical patients may be injured or even die due to the lack of power supply or lack of blood. Falling television equipment may cause patient death.



of TV



Review the items already detailed above that are smalled within the Dialysis Delt.

Mobile item such as dialysis machines and equipment, tables, thates, among others should be fastened to the walls with the appropriate supports to prevent movement.

Equipment situated on top of tables, this is secured in the same way as computers.

Experience Required Work can be carried out by Anyone

Recommended Priority Loss of function, avoids disruption of service

Implementation Cost and Disruption Cost of Implementation to low and involves labor, marcney, bolts, fasteners and impublish persisted. Our option to hospital and equipment in minimal.

TECHNOLOGIES, MONITORING, PROTECTION (BIG PICTURE)



Japan Society of Seismic Isolation

CONSTRUCTION AND DESING ISSUES

- Qualified professionals doing the supervision ٠
- **Materials** •
 - Sea water Sea sand

The poor structural performance was mainly due to the existence of many vulnerable structures and common problems of irregularity and limited ductility.

- ٠
- Inspection during the construction Code issues addressing the probability of failure Role of the professionals in the designs Peer review of actual designs ٠
- ٠
- •
- **Education and Research** •

The earthquake also affected water and electricity supply, leaving many people without drinkable water and telecommunication. The nearly 50sec earthquake left 667 fatalities, over 16000 injured and 20000 displaced. The economic loss was estimated as 3billion US dollars.

The poor structural performance was mainly due to the existence of many vulnerable structures and common problems of irregularity and limited ductility. Although none of the hospital facilities collapsed, 22 were left inoperative in the province of Manabí and Esmeraldas due to severe damage to non-structural components. Medical assistance was provided from temporary shelters, resulting in overcrowding, lack of sanitation and increasing risk of epidemic disease transmission.

Some landslides and lateral spreading caused partial disruption of the transportation system hindering access to the affected areas.

The overall performance of bridges was satisfactory, except the collapse of an overpass reinforced concrete structure in the city of Guayaquil, 280km from the epicenter.

REFERENCIAS:

AISC. (2011). Seismic Design Manual, 2nd ed. Chicago, IL : American Institute of Steel Construction.

AISC. (2011). Steel Construction Manual, 14th ed. Chicago, IL : American Institute of Steel Construction.

ASCE. (2010). Minimum Design Loads for Buildings and Other Structures. ASCE/SEI Standard 7-10, American Society of Civil Engineers. Reston, VA., 656 p.

Bruneau, M., Uang, C.M., & Sabelli, R. (2011). Ductile Design of Steel Structures. New York, NY : McGraw-Hill.

Constantinou, M., Ecker, R., Filiatrault, A., and Kalpakidis, I., (2011). LRFD-Based Analysis and Desing Procedures for Bridge Bearings and Seismic Isolators, 237 p., Buffalo.

Christovasilis, I.P., Filiatrault, A., and Wanitkorkul, A. (2007). Seismic Testing of a Full-Scale Two-Story Light-Frame Wood Building: NEESWood Benchmark Test. NEESWood Report No. MCEER-09-0005, Multidisciplinary Center for Earthquake Engineering Research, University at Buffalo, State University of New York, Buffalo, NY, 216 p.

Disaster types and impacts. (2010, January). Retrieved from www.housingreconstruction.org: ,<u>http://www.housingreconstruction.org/housing/-sites/housingreconstruction.org/files/Disaster%20Types%20and%20Impacts.pdf</u>

Ecuador's Army Corps of Engineering. (2012). Retrieved from <u>www.cee.gov.ec/</u>

FEMA, (2011). Reducing the Risks of Nonstructural Earthquake Damage – A Practical Guide, Federal Emergency Management Agency, Washington, DC, 755 p

Filiatrault, A., and Christopoulos, C., (2006). Principles of Passive Suplemental Damping and Seismic Isolation., pp.331-349.

Filiatrault, A., (2013). "Class notes of Seismic Desing and Analysis of Nonstructural Building Components". University at Buffalo, State University of New York, Buffalo, NY.